



As a quality, leading remanufacturer, we see first hand why so many Fan Clutches are failing prematurely.

Our engineers discovered that the key reason for premature spring-engaged fan clutch failures is **LACK OF TORQUE**. There are fan blades in operation today that require more torque than current fan clutches can produce.

We developed the Gold Top® Rebuild Kit to out-perform the competition!

Highest Torque Rating

With over 5,000 inch-pounds of torque, the Gold Top® Rebuild Kit will handle all fan blades!!

Less Time To Install

Our exclusive design combines nine separate components into **ONE FINAL ASSEMBLY** – this dramatically reduces installation time and installation errors.

Higher Quality Internal Components

- Kevlar impregnated friction material
- 4-point urethane seal
- Elimination of one seal equals one less leak path
- Cast on cast construction reduces corrosion and wear

Lower Cost

Upgrading your fan clutch is as simple as installing the Gold Top® Rebuild Kit.

- Lower cost vs. new
- Lower cost vs. remanufactured
- Less failures
- Less time to install

Ring Power®
Truck Centers



KIT MASTERS

Gold Top
by Kit Masters®

The Torque Leader Solves the Problem!



Replacement for Horton 994985
\$325.00*

Our Gold Top® Rebuild Kit is unmatched by any competitors (new or remanufactured) & packs over 5,000 inch-pounds of Torque!

CALL TODAY!!!

904.737.7730

* Installation available. Contact your local Ring Power Service Center for details.

PARTS AND SERVICE LOCATIONS

ST. AUGUSTINE
Corporate HQ 904.737.7730
TALLAHASSEE
850.562.2121
PERRY
850.584.2800
LAKE CITY
386.755.3997
LAKELAND
863.606.0512

JACKSONVILLE
904.714.2600
GAINESVILLE
352.371.9983
OCALA
352.732.4600
DAYTONA
386.947.3363
BROOKSVILLE
352.796.4978

ORLANDO
407.855.6195
TARPON SPRINGS*
PARTS ONLY STORE
727.938.1515
TAMPA
813.671.3700
PALM BAY
321.952.3001
SARASOTA
941.359.6000

Ring Power
Truck Centers



KIT MASTERS


EXCEEDING EXPECTATIONS WITH HIGHER QUALITY PRODUCTS & SERVICE



THE HIGH-TORQUE 8801X IS NOW AVAILABLE!

Kit Masters' 8801X extended shaft allows for the addition of a urethane o-ring for resilience to motion, and a Viton o-ring to create a superior air barrier.

8801X Shaft Design allows for **DUAL SEAL PROTECTION**



Replacement for Kysor K30
\$269.00*

* Installation available. Contact your local Ring Power Service Center for details.



8801X

REMANUFACTURED FAN CLUTCH

At Kit Masters we are always striving to make good products even better. That is why we made our 8801X remanufactured fan clutch the highest torque rated K26 replacement on the market. You can also upgrade your 8501X to the new 8801X and benefit from our redesigned friction material that dramatically increases torque. Plus, our Dual Seal air shaft extends fan clutch life past the competition.

FEATURES INCLUDE:

- Torque Rated for 30" Fans and Larger
- Redesigned Shaft for Dual Seal Protection
- Superior O-Ring Materials
- Higher Quality Lining
- SKF & INA Bearings vs. Imported Bearings
- Truer Air Shaft
- 200,000 Mile – 24 Month Warranty

904.737.7730

PARTS AND SERVICE LOCATIONS

ST. AUGUSTINE
Corporate HQ 904.737.7730
TALLAHASSEE
850.562.2121
PERRY
850.584.2800
LAKE CITY
386.755.3997
LAKELAND
863.606.0512

JACKSONVILLE
904.714.2600
GAINESVILLE
352.371.9983
OCALA
352.732.4600
DAYTONA
386.947.3363
BROOKSVILLE
352.796.4978

ORLANDO
407.855.6195
TARPON SPRINGS*
PARTS ONLY STORE
727.938.1515
TAMPA
813.671.3700
PALM BAY
321.952.3001
SARASOTA
941.359.6000

RPTRUCKS.COM
EXP. 8-31-2012